



- NOTES:**
- 1.) DO NOT SCALE DRAWING.
  - 2.) REMOVE ALL BURRS, NO SHARP EDGES.
  - 3.) MUST NOT HAVE SCRATCHES, DINGS, OR DENTS.
  - 4.) PART TO BE FREE FROM SURFACE IMPERFECTIONS OTHER THAN SURFACE FINISH REQUIREMENTS.
  - 5.) CRITICAL DIMENSIONS ARE INDICATED BY: .
  - 6.) ALL ITEMS ARE TO BE INSPECTED TO 2.5 AQL SAMPLING PLAN UNLESS OTHERWISE STATED.
  - 7.) ENSURE PACKAGING WILL PROVIDE ADEQUATE PROTECTION DURING TRANSPORT.
  - 8.) GEOMETRIC FEATURES NOT DIMENSIONED ARE CONTROLLED BY 3D MODEL.

DEPT.	NAME	DATE
SALES		
ENG.		
Q.A.		